Attorney Docket No. 1450.1006

Of Correction

ATTENTION

**BRANCH** 

CERTIFICATE OF CORRECTION



IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

fire Patent Application of:

Hideyuki IINO et al.

Application No.: 09/678,733

Confirmation No.: 6735

Filed: October 4, 2000

U.S. Patent No.: 6,877,112 61

Issued: April 5, 2005

For: RESET CONTROL SYSTEM AND METHOD

REQUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents PO Box 1450 Alexandria, VA 22313-1450

Sir:

Patentee(s) respectfully request(s) that a Certificate of Correction be issued in the subject patent, pursuant to 35 U.S.C. §254 and 37 C.F.R. §1.322, to correct the mistake(s) shown on the attached Form PTO-1050.

Since the mistakes are Patent Office mistakes, it is believed that no fee is required.

Respectfully submitted,

STAAS & HALSEY LLP

Date: 64,31,2005

By:

Ti.u. Olaas

Registration No. 22,010

1201 New York Ave, N.W., Suite 700

Washington, D.C. 20005 Telephone: (202) 434-1500

Facsimile: (202) 434-1501

PTO/SB/ 44 (08-00)
Approved for use through 09/30/2000. OMB 0651-0033
U.S. Patent and Trademark Office; U.S. DEPARTMENT OF COMMERCE
Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.
(Also Form PTO-1050)

## UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO : 6,877,112 🖔 🕻

**DATED**: April 5, 2005

INVENTOR(S): Hideyuki IINO et al.

Cover Page, (57) ABSTRACT, line 8, after "reset" insert - - instruction from - -

MAILING ADDRESS OF SENDER: STAAS & HALSEY LLP 1201 New York Ave., N.W. Suite 700 Washington, DC 20005

PATENT NO. 6,877,112

No. of add'l copies @ 50¢ per page